

UNCLASSIFIED

AD NUMBER

AD214225

NEW LIMITATION CHANGE

TO

**Approved for public release, distribution
unlimited**

FROM

AUTHORITY

Per document marking

THIS PAGE IS UNCLASSIFIED

REPRODUCTION QUALITY NOTICE

This document is the best quality available. The copy furnished to DTIC contained pages that may have the following quality problems:

- Pages smaller or larger than normal.**
- Pages with background color or light colored printing.**
- Pages with small type or poor printing; and or**
- Pages with continuous tone material or color photographs.**

Due to various output media available these conditions may or may not cause poor legibility in the microfiche or hardcopy output you receive.



If this block is checked, the copy furnished to DTIC contained pages with color printing, that when reproduced in Black and White, may change detail of the original copy.

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.



FORWARDED BY THE CHIEF, BUREAU OF SHIPS

THE ASSIGNED SECURITY CLASSIFICATION OF Unclassified
IS PROPER AND CORRECT.

THE SECURITY CLASSIFICATION OF THE TITLE OR ASSIGNED
SUBJECT IS Unclassified
THE SECURITY CLASSIFICATION OF THE ABSTRACT IS Unclassified

THIS DOCUMENT MAY BE RELEASED WITH NO
RESTRICTIONS OF DISSEMINATION


AD No. 214 225

ASTIA FILE COPY

LOAN COPY	
Return to 6/1959	
ASTIA	
ARLINGTON HALL STATION	
ARLINGTON 12, VIRGINIA	
Attn: TISSS	
FILE COPY	
Return to	
ASTIA	
ARLINGTON HALL STATION	
ARLINGTON 12, VIRGINIA	
Attn: TISSS	

Portsmouth Naval Shipyard
Portsmouth, New Hampshire

F C
A E
I L L E G



Navy—OPPO 1ND, Portsmouth, N. H.

**HIGH IMPACT SHOCK TESTS ON TOGGLE
SWITCHES - REED SWITCH CALIBRA-
TION, EXHIBITOR - NSMB67-017**

Evaluation Report No. " ETL-2084

10 October 1988

APPROVAL INFORMATION

Submitted by

**K. SHIMA
Electrical Engineer**

Approved by

**A. W. CROCKER
Electrical Engineer**

ELECTRICAL TESTING LABORATORY
PORTSMOUTH, N. H.

BUSHIPS Itr	562/2-1(665J); cov 665-3141
Date:	26 Jul 1956
Index No.	NSN667-017
STL Report	2994

Report of Tests

on

Toggle Switches

submitted by

Micro Switch Corporation, Freeport, Illinois

Ref: (a) BUSHIPS Itr 562/2-1(665J); cov 665-3141 of 31 Jul 1956
(b) BUSHIPS Itr 562/2-1(565J); cov 565-2114 of 26 Jun 1957
(c) BUSHIPS Itr 562/2-1(563J); cov 563-4387 of 18 Nov 1957
(d) Specification MIL-S-901B of 19 Dec 1955
(e) FTSC NAVSHIPS Itr 360; SS/562/2-1(20813) of 28 Aug 1957,
forwarded ⁱⁿ Report No. 2726 to BUSHIPS (Code 312)

Incl: (1) Photograph showing six types of toggle switches as received for tests - Negative No. 3133
(2) Photograph showing five types of toggle switches as received for tests - Negative No. 3134
(3) Photograph showing six types of toggle switches as received for tests - Negative No. 3135
(4) Photograph showing three types of toggle switches as received for tests - Negative No. 3136
(5) Oscillogram showing contact opening or transfer during high impact shock test
(6) Photograph showing typical failures encountered during high impact shock test - Negative No. 3174
(7) Tabulated results of high impact shock tests

1. Antiquity - reference (a)

Priority -	regular
Index No. -	NSN667-017
Cost classification -	Allotment J2291/sPN59.23

enclosure (1)

ELECTRICAL TESTING LABORATORY
PORTSMOUTH, N. H.

Subj: Test 3996; Toggle switches; N31037-017

Date samples received - 13 August 1958
Date tests started - 22 September 1958
Date tests completed - 30 September 1958

2. Purpose - The purpose of this investigation was to ascertain which of the standard toggle switches would withstand the high impact shock requirements of reference (d).

3. Description of Material - The material received for tests comprised two each of the following switches, manufactured by Micro Switch Corporation:

Manufacturer-

Curer's Type	All Type	N3 Type	JAN Type
117S1-1	3021-1	35058-21	ST40E
117S1-3	3021-3	35059-23	ST40D
117S1-21	3021-10	35058-24	-
317S1-3	3022-3	35102-23	ST45D
327S1-1	3023-1	35103-21	T850P
327S1-3	3023-3	35103-23	T850N
327S1-21	3023-11	35103-24	-
127S1-1	3027-1	35059-21	ST50P
127S1-3	3027-3	35059-23	ST50N
127S1-21	3027-9	35059-24	-
337S1-1	3226-1	35103-21	-
337S1-3	3226-3	35103-23	-
337S1-21	3226-4	35103-24	-
17L1-1			
17L1-3			
17L1-21			
27L1-1			
27L1-3			
27L1-21			
317S1-21			

Photographs, enclosures (1) thru (4), illustrate one sample of each of the twenty types of switches received for tests.

4. Method of Testing - The switch samples were mounted on a steel plate, as shown on figure 60 of reference (d), and were subjected to impacts of 400, 1200 and 2000 foot-pounds, applied on each face, the back, top and side of the equipment. Test on any sample was dis-

(1)

ELECTRICAL TESTING LABORATORY
PORTSMOUTH, N. H.

Subj: Test 2994; Toggle switches; USN087-017

continued if failure occurred. For the types of switches with a locking "On" position, one sample was checked in the "On" position, and the other sample was tested in the "Off" position. After each blow, circuit continuity was checked. A brush recorder was connected in the circuit to register contact opening or transfer during each impact on each switch.

5. Results of Tests - The results of tests are tabulated on enclosure (7). These results may be summarized briefly, as follows:

- a. Of the one sample of each type of switch tested in the normally closed position, an indication of contact bounce and/or switch opening was noted on each type as a result of some one or more of the nine impacts delivered to each sample.
- b. Of the one sample of each type of switch tested in the normally open position, only seven types, namely, 28L1-3, 28L1-21, 11T81-1, 32T81-1, 33T81-1, 33T81-3 and 33T81-21, mal-functioned. The mal-functioning included fractures, stripping of the shear threads, loss of circuit continuity and inability to operate the switches manually.

Oscillograms were taken of each impact, but to eliminate including 180 such oscillograms in the report, only typical shots are included, covering at least one impact on each type of switch. The remaining oscillograms are on file in the laboratory and will be forwarded on request. Photograph, enclosure (6), indicates typical failures occurring on the switch samples.

6. Conclusions - Based on the results of tests on sample toggle switches, it may be concluded that

- a. each type of the 20 types of toggle switches, when tested in the normally closed position, would not be satisfactory for use in vital circuits because of momentary contact bounce during high impact shock test.
- b. toggle switches, types 28L1-3, 28L1-21, 11T81-1, 32T81-1, 33T81-1, 33T81-3 and 33T81-21, were unsatisfactory because of structural and/or mechanical failures.

ELECTRICAL TESTING LABORATORY
PORTSMOUTH, N. H.

subj: Test 2924; Toggle switches; NSM607-017

7. Discussion - Letter, reference (a), forwarded two samples each of 20 types of toggle switches, manufactured by Micro Switch Corporation, for shock resistance evaluation. References (b) and (c) authorized tests on only three and four pole switches, under the premise that if these passed, the single and double pole switches would be adjudged shock resistant. However, because of the failures reported by reference (a), the Bureau requested evaluation of the manufacturer's one and two pole switches.

The switches, as received, contained two samples each of the twenty types listed under "Description of Material". Consequently, one sample of each type was connected in a circuit to provide any indication of contact bounce of the normally closed contacts during high impact shock, while the duplicate sample was connected to indicate any momentary closing or transfer of the normally open contacts. Oscillograms were recorded of each impact on each switch sample. The records have been retained in the laboratory for record purposes, since no advantage would be gained by including in the report the 150-odd oscillograms. Typical records showing at least one impact on each of the twenty types of switches have been included as enclosure (3). These oscillograms indicate contact bounce on one or more impacts on all samples tested with the contacts normally closed, as well as operation of the switch from the normally closed to the open position. Thirteen of the twenty types of switches tested in the open position did not indicate any damage or contact bounce. The seven remaining types mal-functioned.


8. Recommendation - On the basis of tests, as conducted, it is recommended that

- a. none of the twenty types of toggle switches be considered suitable for use in vital shipboard circuits because of momentary contact bounce and/or switch transfer from "on" to "off".
- b. the types 274-1-3, 224-1-21, 41781-1, 32781-1, 33781-1, 33781-3 and 33781-21 switches be considered unsatisfactory because of fracture of and mechanical or electrical mal-functioning.
- c. Request - Two each of twenty types of toggle switches, manufactured by Micro Switch Corporation, and submitted as enclosure (1) of reference (a), were received for shock resistance evaluation.

ELECTRICAL TESTING LABORATORY
PORTSMOUTH, N. H.

Subj: Test 2994; Toggle switches; NSM67-017

Samples were subjected to high impact shock in accordance with reference (d), with oscillograph recordings taken of each impact. Results indicated seven types to be unsatisfactory because of fractured housings or other mal-functioning. The remaining types indicated contact bounce and/or switch operation from "on" to "off" as a result of impact and were recommended as unsatisfactory for use in vital circuits. Switches are being returned to the Bureau of Ships as enclosure (8) of letter forwarding this report for examination and disposition.



VIEW OF MICRO SWITCH CORPORATION TOGGLE SWITCHES AS RECEIVED FOR SHOCK RESISTANCE EVALUATION

ASC-9-5-58 - 3153

ITL1-1 ITL1-2
ITL1-3 ZTL1-1
ZTL1-2 ZTL1-3

NSM687-017

TEST NO. 2994

ENCLOSURE (1)

RECORDED

VIEW OF MICRO SWITCH CORPORATION TOGGLE SWITCHES AS RECEIVED FOR SHOCK RESISTANCE EVALUATION

31TS1-3

11TS1-1

11TS1-3

TEST NO. 294

TEST NO.

ASC-9-5-58 - 31A

6

5





4

3

2

1

INCH →



RECEIVED (3)

L2TS1-21
37TS1-21

L2TS1-3
37TS1-3



TEST NO. 294


NSN 67-017


VIEWS OF NICO SWITCH CORPORATION TOGGLE SWITCHES AS RECEIVED FOR SHOCK RESISTANCE EVALUATION

ASC-9-5-58 - 3155

L2TS1-1
37TS1-1







Oscillograms showing contact opening or transfer

NSM 687-017 TEST No. 2394

ENCLOSURE 65

SAMPLE NO. 1 - N.C.

IMPACT CAUSED SWITCH TO OPEN

MICRO SWITCH Corp.
MFG. TYPE ITL-21

CHART NO BL 924

BRUSH ELECTRONICS COMPANY

SAMPLE NO. 2 - N.O.

2.4 CYCLES

TIME →

SAMPLE NO. 1, N.C.

60 CYCLES PER SEC.



MICRO SWITCH Corp.
MFG. TYPE ITL-21
ELECTRONICS COMPANY

CHART NO BL 924

BRUSH ELECTRONICS COMPANY

SAMPLE NO. 2 N.O.

2.4 CYCLES

TIME →

BOTH SAMPLES BECAME DISASSEMBLED DURING IMPACT.

OSCILLOGRAMS SHOWING CONTACT OPENING OR TRANSFER

TEST NO. 2994

ENCLOSURE (5)
SHEET 2

NSM 687-017

SAMPLE No. 1 N.C.

60 CYCLES PER SECOND

MICRO SWITCH CORP.
MFG. TYPE 2TLI-1

CHART NO. BL 924
400 FT. L. - Top
BRUSH ELECTRONICS COMPANY

SAMPLE No. 2 N.O.

24 CYCLES

TIME →

SAMPLE No. 1 N.O.

60 CYCLES PER SECOND

MICRO SWITCH CORP.
MFG. TYPE 2TLI-3
CHART NO. BL 924
BRUSH ELECTRONICS COMPANY

SAMPLE No. 2 N.O.

24 CYCLES

TIME →

Oscillograms showing contact opening or transfer


NSM 687-017

TEST No. 2994

ENCLOSURE (5)
SHEET 3


SAMPLE No. 1 INC.

1 CYCLES PER SECOND




SAMPLE No. 2 INC.

1 CYCLES PER SECOND



SAMPLE No. 1 INC.

1 CYCLES PER SECOND





Oscillograms showing contact opening or transfer

TEST No. 2994



ENCLOSURE (5)
SHEET 4

NSM 687-017



Oscilloscopes showing contact opening or transfer
TEST No 2994
NSM 687-C17

ENCLOSURE (5)
SHEET 5



Oscillograms showing contact opening or transfer
TEST No 2994
NSM 687-017
ENCLOSURE (F)
SHEET 6

SAMPLE NO. 1 N.C.

60 CYCLES PER SECOND

MICRO SWITCH CORP.
MFG. TYPE JITSI-2
BRUSH ELECTRONICS COMPANY

→ 2.4 CYCLES

1200 FT/LB → Tension
CHART NO. BL 924

SAMPLE NO. 2 N.C.

TIME →

SAMPLE NO. 1 N.C. → 60 CYCLES PER SECOND

MICRO SWITCH CORP.
MFG. TYPE JITSI-21
BRUSH ELECTRONICS COMPANY
PRINTED IN U.S.A.

SAMPLE NO. 2 N.O.

→ 2.4 CYCLES

2000 FT/LB → Tension
CHART NO. P 924

TIME →

Oscillograms showing contact opening or transfer

TEST No. 2994

ENCLOSURE (6)
SHEET 7

NSM 687-017

SAMPLE NO. 1 N.C.
(NAT AN. CONTACT)

MICRO SWITCH CORP.
MFG. TYPE 3ETSI-1

ART NO. H. 9. 4 BRUSH ELECTRONICS COMPANY
MANUFACTURED IN U.S.A.

SAMPLE NO. 2 N.O.

→ 2.4 CYCLES.

SAMPLE NO. 1 N.C.
60 CYCLES PER SECOND

↓

MICRO SWITCH CORP.
MFG. TYPE 3ETSI-3

SAMPLE NO. 2 N.O.

→ 2.0 CYCLES

CHART NO.
100 F.F. ← BLOCKS

Time →

Oscillograms showing contact opening or transfer

TEST No. 2994

NSM 687-017

ENCLOSURE 5
SHEET 8

SAMPLE No 1 - N.C.

60 CYCLES PER SECOND

MICRO SWITCH CORP.
MFG. TYPE 32TS1-21

PRINTED IN U.S.A.
HARDI ELECTRONICS COMPANY

SAMPLE No 2 - N.O.

1200 FT. LB. - BACK

TIME →
1 → 2.4 Cycles

SAMPLE No 1 N.C.
IMPACT CAUSED SWITCH TO OPEN

60 CYCLES PER SECOND

MICRO SWITCH CORP.
MFG. TYPE 33TS1-1

CHART NO 121-1
PRINTED IN U.S.A.
HARDI ELECTRONICS COMPANY

SAMPLE No 2 N.O.
(Not in Circuit)

1 → 2.4 Cycles

2000 FT. LB. - TOP

TIME →

OSCILLOGRAMS SHOWING CONTACT OPENING OR TRANSFER

NSM 687-017

TEST No. 2994

ENCLOSURE SHEET 3

60 CYCLES PER SECOND

SAMPLE NO. 1 NO.

MICRO SPONGE CHIP

MEG. TIME 237.51-3

CHART

NO. BL 92

BRUSH ELECTRONICS COMPANY

PRINTED IN U.S.A.

PAPER CHOSEN SWING TO OPEN
ADLT. LB. - BACK

2.4 CYCLES

TIME →

SAMPLE NO. 1 NO.

(SPONGE NOT IN CIRCUIT)

MICRO SWITCH CHIP
MEGA TIME 237.51-3

PRINTED IN U.S.A.

SAMPLE NO. 2 NO.

2000 FT. LBS.
CHART NO. BL 92
HKL

TIME →


2.4 CYCLES

OSCILLOGRAMS SHOWING CONTACT OPENING OR TRANSFER

SM 687-017

TEST No. 2994

ENCLOSURE
MEEF



100-25-50 - 314
TYPICAL EXAMPLES OF IMAGE MICRO SWITCH CORPORATION TOGGLE SWITCHES AS A RESULT OF HIGH IMPACT SHOCK TEST

11TS1-1

NSM687-017

21L1-2.

TEST NO. 2994

33TS1-21

ENCLOSURE (6)

33TS1-1

Report of high impact shock test on toggle switches, mounted on a steel plate, as shown in figure
60 of reference (d) -

Manufacturer's Switch Type No.	Sample No.	Test Po- sition	Direction of Impact	Impact (Foot- Pounds)	Remarks
ITL1-1	1	E. C.	Back	400	Switch opened under impact
		N. C.	Back	1200	Switch opened under impact
		N. C.	Back	2000	Switch opened under impact
		N. C.	Top	400	Indication of contact bounce
		N. C.	Top	1200	Indication of contact bounce
		N. C.	Top	2000	Switch opened under impact
		H. C.	Side	400	No damage or indication of contact bounce
		N. C.	Side	1200	Switch opened under impact
		N. C.	Side	2000	Switch opened under impact
		H. C.	Side	400	No damage or indication of contact bounce
ITL1-2	2	H. O.	Back	400	No damage or indication of contact bounce
		H. O.	Back	1200	No damage or indication of contact bounce
		H. O.	Back	2000	No damage or indication of contact bounce
		H. O.	Top	400	No damage or indication of contact bounce
		H. O.	Top	1200	No damage or indication of contact bounce
		H. O.	Top	2000	No damage or indication of contact bounce
		H. O.	Side	400	No damage or indication of contact bounce
		H. O.	Side	1200	No damage or indication of contact bounce
		H. O.	Side	2000	No damage or indication of contact bounce
		H. O.	Side	400	Indication of contact bounce
ITL1-3	1	H. C.	Back	400	Indication of contact bounce
		H. C.	Back	1200	Indication of contact bounce
		H. C.	Back	2000	Indication of contact bounce
		H. C.	Top	400	No damage or indication of contact bounce
		H. C.	Top	1200	Indication of contact bounce
		H. C.	Top	2000	Indication of contact bounce
		H. C.	Side	400	No damage or indication of contact bounce
		H. C.	Side	1200	No damage or indication of contact bounce
		H. C.	Side	2000	No damage or indication of contact bounce
		H. C.	Side	400	No damage or indication of contact bounce
ITL1-3	2	H. O.	Back	400	No damage or indication of contact bounce
		H. O.	Back	1200	No damage or indication of contact bounce
		H. O.	Back	2000	No damage or indication of contact bounce
		H. O.	Top	400	No damage or indication of contact bounce
		H. O.	Top	1200	No damage or indication of contact bounce
		H. O.	Top	2000	No damage or indication of contact bounce
		H. O.	Side	400	No damage or indication of contact bounce
		H. O.	Side	1200	No damage or indication of contact bounce
		H. O.	Side	2000	No damage or indication of contact bounce
		H. O.	Side	400	No damage or indication of contact bounce

Enclosure (7)

Model Number	Switch Type	Sample No.	Test Po- sition	Direction of Impact	Impact (Spec- tacular pounds)	Insights
IRL1-21	N. C.	1	N. C.	Back	400	Indication of contact bounce
			N. C.	Back	1200	Switch opened under impact
			N. C.	Back	2000	Switch opened under impact
			N. C.	Top	400	No damage or indication of contact bounce
			N. C.	Top	1200	Indication of contact bounce
		2	N. C.	Top	2000	Indication of contact bounce
			N. C.	Side	400	No damage or indication of contact bounce
			N. C.	Side	1200	Indication of contact bounce
			N. C.	Side	2000	Switch opened under impact
			N. O.	Back	400	No damage or indication of contact bounce
IRL1-1	N. C.	1	N. O.	Back	1200	No damage or indication of contact bounce
			N. O.	Back	2000	No damage or indication of contact bounce
			N. O.	Top	400	No damage or indication of contact bounce
			N. O.	Top	1200	No damage or indication of contact bounce
			N. O.	Top	2000	No damage or indication of contact bounce
		2	N. O.	Side	400	No damage or indication of contact bounce
			N. O.	Side	1200	No damage or indication of contact bounce
			N. O.	Side	2000	No damage or indication of contact bounce
			N. C.	Back	400	Indication of contact bounce
			N. C.	Back	1200	Switch opened under impact
IRL1-1	N. O.	1	N. C.	Back	2000	Switch opened under impact
			N. C.	Top	400	Indication of contact bounce
			N. C.	Top	1200	Indication of contact bounce
			N. C.	Top	2000	Indication of contact bounce
			N. C.	Side	400	Indication of contact bounce
		2	N. O.	Back	400	Indication of contact bounce - insulation after test indi- cated mounting bracket had distorted slightly.
			N. O.	Back	1200	No damage or indication of contact bounce
			N. O.	Back	2000	No damage or indication of contact bounce
			N. O.	Top	400	No damage or indication of contact bounce
			N. O.	Top	1200	No damage or indication of contact bounce
			N. O.	Top	2000	No damage or indication of contact bounce
			N. O.	Side	400	No damage or indication of contact bounce
			N. O.	Side	1200	No damage or indication of contact bounce
			N. O.	Side	2000	No damage or indication of contact bounce - Examination after test indicated mounting bracket had distorted slightly.

Enclosure (7)
Sheet 2

Manufacturer's Switch Type	Sample No.	Test Po- sition	Direction of Impact	Impact (Foot- Pounds)	Remarks
27U1-3	1	N. C.	Back	400	No damage or indication of contact bounce
		N. C.	Back	1200	Indication of contact bounce
		N. C.	Back	2000	Indication of contact bounce. Locking nut came loose from shaft threads permitting switch to become disengaged from shock plate. Resecured to test plate. Test continued.
		N. C.	Top	400	No damage or indication of contact bounce
		N. C.	Top	1200	Indication of contact bounce
		N. C.	Top	2000	Indication of contact bounce
		N. C.	Side	400	Indication of contact bounce
		N. C.	Side	1200	Indication of contact bounce
		N. C.	Side	2000	Indication of contact bounce. Examination indicated distortion of the mounting shaft threads.
27U1-1	2	N. O.	Deck	400	No damage or indication of contact bounce
		N. O.	Back	1200	No damage or indication of contact bounce
		N. O.	Back	2000	No damage or indication of contact bounce
		N. O.	Top	400	No damage or indication of contact bounce
		N. O.	Top	1200	No damage or indication of contact bounce
		N. C.	Top	2000	No damage or indication of contact bounce. Two of the rivets securing this mounting plate to the switch body loosened and fell out.
		N. O.	Side	400	No damage or indication of contact bounce
		N. O.	Side	1200	No damage or indication of contact bounce
		N. O.	Side	2000	Interior of switch fell out, after remaining two rivets broke.
27U1-21	1	N. C.	Back	400	Indication of contact bounce. Switch mounting plate loosened from switch body.
		N. C.	Back	1200	Switch became disengaged. Test discontinued.
		N. O.	Back	400	No damage or indication of contact bounce
		N. O.	Back	1200	Switch became disengaged. Test discontinued. Switch housing fractured.
11781-1	1	N. C.	Back	400	Switch opened under inspect. Sample appears to be loose on mounting shaft.
		N. C.	Back	1200	Switch became disengaged. Test discontinued.
11781-1	2	N. O.	Back	400	Switch mounting shaft appears to be loose at body entrance.
		N. O.	Back	1200	No damage or indication of contact bounce
		N. O.	Back	2000	Switch became disengaged. Test discontinued.

Manufacturer	Sample No.	Test Position	Direction of Impact	Impact (Foot-Pounds)	Damage
LITSI-3	1	H. C.	Back	400	Indication of contact bounce
		N. C.	Back	1200	Indication of contact bounce
		M. C.	Back	2000	Indication of contact bounce
		H. C.	Top	400	Indication of contact bounce
		N. C.	Top	1200	Indication of contact bounce
		M. C.	Top	2000	Indication of contact bounce
		H. C.	Side	400	Indication of contact bounce
		N. C.	Side	1200	Indication of contact bounce
		M. C.	Side	2000	Indication of contact bounce
		H. O.	Back	400	No damage or indication of contact bounce
LITSI-3	2	N. O.	Back	1200	No damage or indication of contact bounce
		N. O.	Back	2000	No damage or indication of contact bounce
		N. O.	Top	400	No damage or indication of contact bounce
		N. O.	Top	1200	No damage or indication of contact bounce
		H. O.	Top	2000	No damage or indication of contact bounce
		H. O.	Side	400	No damage or indication of contact bounce
		N. O.	Side	1200	No damage or indication of contact bounce
		N. O.	Side	2000	No damage or indication of contact bounce
		H. C.	Back	400	Indication of contact bounce
		H. C.	Back	1200	Indication of contact bounce
LITSI-21	1	H. C.	Back	400	Switch opened under impact
		H. C.	Back	1200	No damage or indication of contact bounce
		H. C.	Top	400	Switch opened under impact
		H. C.	Top	1200	No damage or indication of contact bounce
		M. C.	Side	400	Switch opened under impact
		M. C.	Side	1200	No damage or indication of contact bounce
		H. O.	Back	400	No damage or indication of contact bounce
		H. O.	Back	1200	No damage or indication of contact bounce
		H. O.	Top	400	No damage or indication of contact bounce
		H. O.	Top	1200	No damage or indication of contact bounce
LITSI-21	2	N. O.	Side	400	No damage or indication of contact bounce
		N. O.	Side	1200	No damage or indication of contact bounce
		N. O.	Side	2000	No damage or indication of contact bounce

Switch could not be operated and was removed from the plate. Switch could then be operated and was subjected to old impacts.

Manufacturer's Switch Type	Sample No.	Test Po- sitions	Direction of Impact	Impact (Foot- Pounds)	Remarks
LTSI-1	1	H. C.	Back	400	Indication of contact bounce
		H. C.	Back	1200	Switch opened under impact
		M. C.	Back	2000	Switch opened under impact
		H. C.	Top	400	Indication of contact bounce
		H. C.	Top	1200	Indication of contact bounce
		H. C.	Top	2000	Indication of contact bounce
		M. C.	Side	400	Indication of contact bounce
		M. C.	Side	1200	Indication of contact bounce
		M. C.	Side	2000	Switch opened under impact
		H. O.	Back	400	No damage or indication of contact bounce
LTSI-1	2	H. O.	Back	1200	No damage or indication of contact bounce
		M. O.	Back	2000	No damage or indication of contact bounce
		M. O.	Side	400	No damage or indication of contact bounce
		M. O.	Side	1200	No damage or indication of contact bounce
		M. O.	Side	2000	No damage or indication of contact bounce
		N. O.	Top	400	No damage or indication of contact bounce
		N. O.	Top	1200	No damage or indication of contact bounce
		N. O.	Top	2000	No damage or indication of contact bounce - Randomization after completion of test indicated shaft had loosened on switch body on both samples.
		H. O.	Top	400	
		H. O.	Top	1200	
LTSI-3	1	H. C.	Back	400	Indication of contact bounce
		H. C.	Back	1200	Indication of contact bounce
		H. C.	Back	2000	Indication of contact bounce - The shaft was found to be slightly loose on the switch body.
		M. C.	Top	400	Indication of contact bounce
		M. C.	Top	1200	Indication of contact bounce
		M. C.	Side	400	Indication of contact bounce
		M. C.	Side	1200	Indication of contact bounce
		M. C.	Side	2000	Indication of contact bounce
		N. O.	Back	400	No damage or indication of contact bounce
		N. O.	Back	1200	No damage or indication of contact bounce
LTSI-3	2	N. O.	Top	400	No damage or indication of contact bounce - The shaft was found to be slightly loose on the switch body.
		N. O.	Top	1200	No damage or indication of contact bounce
		N. O.	Top	2000	No damage or indication of contact bounce

Model "C" core, & switch type 12TSI-3	Sample No. 2	Test Po- sition	Direction of Impact	Impact (foot- pounds)	Remarks
12TSI-21	1	H. C.	Back	400	Indication of contact bounce
		H. C.	Back	1200	No damage or indication of contact bounce
		H. C.	Side	400	No damage or indication of contact bounce
		H. C.	Side	1200	No damage or indication of contact bounce
		H. C.	Top	400	Indication of contact bounce
		H. C.	Top	1200	No damage or indication of contact bounce
		H. C.	Side	2000	Indication of contact bounce
		H. C.	Side	4000	Switch grounded during impact causing blown fuse.
12TSI-21	2	H. C.	Back	2000	Switch opened during impact. Mustang shaft loosened.
		H. C.	Back	4000	Indication of contact bounce
		H. C.	Side	1200	Indication of contact bounce
		H. C.	Side	2000	Indication of contact bounce
		H. C.	Top	4000	Indication of contact bounce
		H. C.	Top	1200	No damage or indication of contact bounce
		H. C.	Side	2000	Indication of contact bounce
		H. C.	Side	4000	No damage or indication of contact bounce
31TSI-3	1	H. C.	Back	400	Indication of contact bounce
		H. C.	Back	1200	No damage or indication of contact bounce
		H. C.	Side	2000	Indication of contact bounce
		H. C.	Side	4000	No damage or indication of contact bounce
		H. C.	Top	1200	Indication of contact bounce
		H. C.	Top	2000	No damage or indication of contact bounce
		H. C.	Side	4000	No damage or indication of contact bounce
		H. C.	Side	1200	No damage or indication of contact bounce
31TSI-3	2	H. C.	Back	400	Indication of contact bounce
		H. C.	Back	1200	No damage or indication of contact bounce
		H. C.	Side	2000	Indication of contact bounce
		H. C.	Side	4000	No damage or indication of contact bounce
		H. C.	Top	1200	Indication of contact bounce
		H. C.	Top	2000	No damage or indication of contact bounce
		H. C.	Side	4000	No damage or indication of contact bounce
		H. C.	Side	1200	No damage or indication of contact bounce

Enclosure (7)
Sheet 6

Model "C" Core, #	Sample No.	Test Po- sition	Direction of Impact	Impact (Foot- Pounds)	Remarks
31TSI-3	2	M. O. H. O. H. O.	Side Side Side	400 1200 2000	No damage or indication of contact bounce No damage or indication of contact bounce - Examination after test indicated slight distortion of mounting bracket on both samples.
31TSI-21	1	N. C. N. C.	Back Back Back Top Top Top Side Side Side Side Side Side	400 1200 2000 400 1200 2000 400 1200 2000 400 1200 2000	Indication of contact bounce Indication of contact bounce Indication of contact bounce No damage or indication of contact bounce Indication of contact bounce Indication of contact bounce Indication of contact bounce No damage or indication of contact bounce Indication of contact bounce Indication of contact bounce Indication of contact bounce Indication of contact bounce
31TSI-21	2	N. O. H. O. N. O.	Back Back Back Top Top Top Side Side Side Side Side Side	400 1200 2000 400 1200 2000 400 1200 2000 400 1200 2000	No damage or indication of contact bounce No damage or indication of contact bounce
32TSI-1	1	N. C. N. C.	Back Back	400 1200	Switch, when checked for operation after impact, could not be opened - Test discontinued.
32TSI-1	2	N. O. N. O. N. O.	Back Back Back	400 1200 2000	No damage or indication of contact bounce No damage or indication of contact bounce Switch momentarily closed during impact and could not be opened - Test discontinued
32TSI-3	1	N. C. N. C.	Back Back	400 1200	Indication of contact bounce Switch opened under impact. Internal damage detected. Test discontinued

Inclusion (7)
Sheet 7

Model "V"	Curve	Sample No.	Test Position	Direction of Impact	Impact (Foot-Pounds)	Remarks
32T61-3	32T61-3	2	H. O. H. O. H. O. H. O. H. O. H. O. H. O. H. O. H. O. H. O.	Back Back Back Top Top Side Side Side Side	400 1200 2000 400 1200 2000 400 1200 2000	No damage or indication of contact bounce No damage or indication of contact bounce
32T61-21	1		H. C. C. C. C. C. H. C. C. C. C. C.	Back Back Back Top Top Top Side Side Side	400 1200 2000 400 1200 2000 400 1200 2000	Indication of contact bounce Indication of contact bounce Switch opened under impact No damage or indication of contact bounce No damage or indication of contact bounce No damage or indication of contact bounce Indication of contact bounce Indication of contact bounce
32T61-21	2		H. C. C. C. C. C. H. C. C. C. C. C.	Back Back Back Top Top Top Side Side Side	400 1200 2000 400 1200 2000 400 1200 2000	No damage or indication of contact bounce No damage or indication of contact bounce No damage or indication of contact bounce Indication of contact bounce
32T61-1		1	H. C. C. C. C. C. H. C. C. C. C. C.	Back Back Back Top Top Side Side	400 1200 2000 400 1200 2000 2000	Indication of contact bounce Switch opened under impact Switch opened under impact Indication of contact bounce Indication of contact bounce Indication of contact bounce Mounting bracket was distorted and side plate was loose.

Enclosure (7)
Sheet 8

Manufacturer	Sample No.	Test Position	Direction of Impact	Impact (Foot Pounds)	Results
33TEL-1	2	N. O.	Back	400	No damage or indication of contact bounce
		N. O.	Back	1200	No damage or indication of contact bounce
		S. O.	Back	2000	Switch became disassembled as a result of the impact - Test discontinued
33TEL-3	1	E. C.	Back	400	Switch opened during impact. Lack of continuity in switch - Test discontinued
33TEL-3	2	N. O.	Back	400	Switch lost continuity as a result of impact - Test discontinued
33TEL-21	1	S. C.	Back	400	switch opened under impact
33TEL-21	2	S. O.	Back	1200	Switch became disassembled. Test discontinued
		S. O.	Back	400	No damage or indication of contact bounce
		S. O.	Back	1200	No damage or indication of contact bounce
		S. O.	Back	2000	Switch became disassembled. Test discontinued

NOTES: Test Position - N. C. Indicates normally closed contacts.
 Test Position - N. O. Indicates normally open contacts.

UNCLASSIFIED

UNCLASSIFIED